

# Window Covering Measurement Guide

## Things to Remember:


1. Use a steel measuring tape to determine your measurements
2. Determine your type of mounting:
  - Inside Mount – Blinds are mounted inside the window frame
  - Outside Mount – Blinds are mounted outside the window frame
3. All measurements should be of the window, measuring an existing blind may cause your measurements to be incorrect.
4. Measurements should be recorded to the nearest 1/8" and Width should always be listed first.
5. Double-check all your measurements.
6. Need additional help? Contact your Sales Rep or call our Customer Service.

## Measuring for Inside Window Mount

- Width: Measure the width in 3 different places and use the narrowest measurement.
- Height: Measure the exact distance from the top inside edge of the frame to the windowsill in at least 3 different places and use the longest measurement.
- Note: Inside mount blind sizes include 1/2" deduction in width, so do not add any additional deductions in your measurements.

## Measuring for Outside Window Mount

- Width: Measure the exact distance from the outside edge of the left side of the window frame to the outside edge of the right side of the window frame.
- Height: Measure the exact distance from the top outside edge of the window frame to the bottom outside edge of the frame.
- Note: To ensure complete coverage we recommend adding approximately 1-1/2" on each side for width and approximately adding 3" for overall length for faux Wood and mini Blinds. And add 3" to all 4 sides for vertical blinds.



v072016